

**Training Document for
Integrated Automation Solutions
Totally Integrated Automation (TIA)**

CNC Programming Milling

ShopMill

Module S03

This document was prepared by Siemens AG for training purposes for the project 'Siemens Automation Cooperates with Education' (SCE).
Siemens AG does not guarantee the content of this document.

Passing on this document, copying it and using and sharing its content is allowed within public training facilities and continued education facilities. Exceptions require written approval by Siemens AG (Michael Knust michael.knust@siemens.com).

Offenders are held liable. All rights reserved, including translation rights, particularly in the event a patent is granted or a utility model or design is registered.

We thank the Michael Dziallas Engineering corporation, the teachers of vocational schools others for their support during the preparation of this document.

Table of Contents


1	Preface	6
2	Introduction	8
2.1	Development Phases of CNC Technology	8
2.2	Requirements for Controller in the New Millennium	8
2.3	Advantages of CNC Programming with SinuTrain SHOPMILL, SHOPTURN.....	8
3	Operator Components.....	9
4	Program Management - Milling	11
4.1	Directory.....	12
4.2	Program Structure.....	13
4.3	Editing Programs	15
5	Saving Program Data	15
6	Program Structure - Milling	18
6.1	Program Header	18
7	Tool Management – Milling.....	22
7.1	Calling the Tool List	23
7.2	Structure of the Tool List.....	24
7.3	Tool Wear	27
7.4	The Magazine	29
7.5	Setting Up/Deleting a New Tool.....	29
7.5	Setting Up/Deleting a New Tool.....	30
7.6	A Tool with Several Edges.....	32
7.7	Sorting the Tools.....	33
8	Programming Example: Contour Programming.....	35
8.1	Example of Contour Programming	35
8.2	Face Milling.....	36
8.3	Contour Calculator	37
8.4	Path Milling	42
8.5	Forward-Backward.....	43
9	Programming Example Contour Spigot	45
9.1	Contour Spigot Milling – Removing Residual Material	45
9.2	Face Milling.....	46
9.3	First Contour Limit-Contour	48
9.4	Second Contour: Actual Contour Spigots	49
9.5	Spigot – Residual Material.....	51
10	Programming Example Standard Milling Cycles.....	53
10.1	Programming Example for Milling Cycles (Rectangular Spigot, Circular Pocket)	53
10.2	Face Milling.....	55
10.3	Rectangular Spigot	58
10.4	Circular Pocket.....	61
10.5	Processing (Basic Block).....	63
11	Programming Example – Position Patterns for Drilling and Milling Cycles.....	64
11.1	Example: Drilling and Milling Positions	64
11.2	Rectangular Pocket.....	66
11.3	Circular Pockets.....	68
11.4	Position Pattern.....	69
11.5	Drilling and Positions	70
12	Program Example – Centering, Drilling, Threading	72
12.1	Exercises for Centering, Drilling, and Threading	72

12.2	Centering the Frame and the Hole Circle	73
12.3	Drilling	75
12.4	Programming "Drilling the Hole Circle" by Using Copy and Insert	76
12.5	Borings Threads for Frames	77
13	Programming Example – Programmable Transformations, Subprogram Technology...	79
13.1	Program Header	80
13.2	Contour Calculator Left Upper Corner	81
13.3	Path Milling	82
13.4	Mirroring.....	83
13.5	Longitudinal Grooves	87
13.6	Circumferential Groove	89
13.7	Contour Pockets with Contour Calculator.....	90
14	Rotation Contour Pockets	94
15	Making Holes with a Drill	96
16	Subprograms.....	98
17	Mould Making - Milling	100
17.1	Prerequisites	101
17.2	Program Structure Technology Program with Geometry Program.....	102
17.3	Program Structure Complete Program	103
17.4	Creating the Program	105
17.5	High Speed Settings	107
17.6	Calling the Subprogram	111
17.7	Processing the Program	112
17.8	Starting Processing at a Certain Program Location	114
17.9	Simulation of a Volume Model	117
18	Information about Mould Making	118
19	Fundamentals of CNC Machines.....	119
20	Manual Operating Area - Milling.....	120
20.1	Operating Area TSM.....	121
20.2	Operating Area Set NPV.....	124
20.3	Operating Area Zero Point Workpiece.....	125
20.4	Measuring the Tool Length	128
20.5	Measuring the Tool Radius.....	130
20.6	Swiveling.....	131
20.7	Manual Positioning.....	132
20.8	Manual Face Milling.....	133
21	Measuring the Workpieces in the Setup Mode JOG - Milling.....	134
21.1	Measuring Manually – Measuring Automatically	135
21.2	Measuring the Edge.....	136
21.3	Measuring the Corner	139
21.4	Measuring the Pocket and Hole.....	143
21.5	Measuring Spigots	146
21.6	Aligning the Plane.....	150
22	DIN/G-Code – Programming under ShopMill	153
22.1	Generating the Contour with the Contour Calculator.....	156
23	Multiple Clamping	161
24	CAD Reader	163
24.1	General Function	163
24.2	Opening the CAD READER.....	163
24.3	Opening a DXF Drawing from a File.....	165
24.4	Tooleiste	166

24.5	Specifying the Zero Point.....	167
24.6	Contour Tracking	167
24.7	Influencing the Graphic Representation	169
24.8	Editing Input Data	170
24.9	Transferring Contour Elements to the Directory	172
25	Sample Drawings - Milling	173
25.1	Mounting Plate	173
25.2	Hole Plate	174
25.3	Housing Lid	175
25.4	Longitudinal Guide	176
25.5	Example 1	177
25.6	Injection Mould.....	178
25.7	Measuring Part.....	179
25.8	Pattern Plate	180
25.9	Exercise 11	181
26	Flange	182
26.1	Clamping Plate.....	183
26.2	Prism	184
26.3	Kidney Plate.....	185
26.4	Connecting Rod	186
26.5	Wing.....	187

1 Preface

The training document '**Programming with ShopMill**' acquaints you with the software.



Today, CNC controllers are considered the most essential part of any automation. Depending on the problem definition, the most varied tasks in the areas of turning, milling, lasering, and grinding as well as in many other areas can be carried out economically with the controllers ShopMill and ShopTurn.

Training Objective:

Module S03 shows you, step by step, how to program with ShopMill.

Subsequently, the reader is to solve the tasks provided.

Preconditions

To successfully work through this module, the following knowledge is assumed:


- Knowledge in handling Windows
- Fundamentals of CNC programming with Sinutrain (for example, Module S01)

Hardware and software required

- 1 PC, operating system Windows XP Professional starting with SP1 with 500 MHz and 256 MB RAM, free disk storage approx. 400 MB, of that 50 MB on the system drive, 1GB when all products are installed, MS Internet Explorer starting with 6.0
- 2 Software SINUTRAIN 802D/ 810D/840D/ 840Di/ Programming & Training, SinuTrain/JopShop



1 PC



2. SINUTRAIN

2 Introduction

2.1 Development Phases of CNC Technology

- At the beginning of the eighties, first CNC machines with simple controllers
- In the middle of the eighties, more powerful controllers with cycles because of faster processors as well as machine tools with greater processing speed
- At the end of the eighties, machine tools with 5 and more axes and special software tools for external programming by using CAD/CAM systems
- At the beginning of the nineties, flexible manufacturing systems with extensive supplementary functions such as palette systems and multiple clamping with multiple spindle drives
- In the middle of the nineties, continued development of tool systems and the use of special tools for processing complex workpiece contours with only one tool
- End of the nineties: central programming systems for programming several different controllers at different machine tools

2.2 Requirements for Controller in the New Millennium

- Openness: It is to be possible for the machine manufacturer or the user to configure and expand controllers according to their own requirements
- Independence: Programming by means of a uniform controller interface for the most varied CNC processing
- Equality: All machine data is to be available also at the external programming units.
Programming at the external programming units is the same as on the machine tool.
- Saving programming time: With graphic machining plans and help displays, it is to be possible to generate complex workpiece contours very easily and quickly
- Editing capability: Extensive editing functions provide for fast and simple program changes/program expansion

2.3 Advantages of CNC Programming with SinuTrain SHOPMILL, SHOPTURN

The controller is continuously optimized and can be adapted any time to the individual requirements of the machine manufacturers. Moreover, cycles and functions can be integrated later.

Regardless of whether turning, milling, or any other type of processing is performed, always the same program interface and the same menus or functions are used.

Retrofit: This means: Siemens can retrofit also older CNC machines to ShopMill and ShopTurn.

Advantage: Operating the software and the menu structure has to be learned only once.

By transferring the machine data to the programming system of SINUTRAIN, programming at the external programming unit is the same as on the machine tool.

By using contour calculators and CAD readers, simple programming is possible without technical terms. By directly entering technological values, no external calculations have to be made beforehand. The integrated contour calculator is able to process all conceivable dimensions, yet is very simple to handle. Through work step programming and many online help functions, extensive programming tasks can be solved very quickly. Convenient programming is possible with functions such as Copy, Cut, and Insert. Since the program is generated in the editor as a graphic machining plan by means of individual work steps, all editing steps are provided in a straightforward arrangement.

3 Operator Components

In this chapter, the basic operator components are shown. These components are to be considered examples, and are not necessarily on the machine in the design described here.

The manufacturer's specifications have to be noted!

Here an example of an operator panel of the type OP010C.

This operator panel consists of a screen with horizontal




and vertical



softkeys.

They are used for calling the individual cycles, programs, and functions.

Depending on the operator panel, an alpha/numeric block and a correction block is located on the side.



Here an example of a machine control panel.

With the machine control panel the machining of a workpiece is started.




In this chapter, the keys and their functions preassigned by Siemens are not described any further since they are described in detail in the operating instructions “Operation/Programming”.

4 Program Management - Milling

The structure, the management, editing and saving programs under ShopMill is described in detail.

Content of the Module:




4.1 Directory

Programs can be stored in the directories. That keeps the program memory clearly arranged.

By pressing the softkey



the available directories under ShopMill are opened in the operating area



The names of the directories,

Name
BEISPIELPROGRAMME
CAD_PROGRAM
GRAVUR
SHOPMILL
TEMP

the directory type

Typ

WPD

and the generation date and time are displayed.

Name	Typ	Geladen	Größe	Datum/Zeit
BEISPIELPROGRAMME	WPD	X	NCK-Dir.	24.11.2005 15:29
CAD_PROGRAM	WPD	X	NCK-Dir.	07.12.2005 15:01
GRAVUR	WPD	X	NCK-Dir.	25.11.2005 08:24
SHOPMILL	WPD	X	NCK-Dir.	23.11.2005 14:30
TEMP	WPD	X	NCK-Dir.	24.11.2005 15:29

Datum/Zeit
07.12.2005 15:27
16.11.2005 08:45
17.11.2005 13:41

Directory Structure

The size of the directory is not displayed.

The X in the area “Loaded” tells us that the directory is loaded on the NC of the machine.

Geladen	Größe
X	NCK-Dir.
X	NCK-Dir.

VERZEICHNIS					
Name	Typ	Geladen	Größe	Datum/Zeit	
BEISPIELPROGRAMME	MPD	X	NCK-Dir.	24.11.2005 15:29	
CAD_PROGRAM	MPD	X	NCK-Dir.	07.12.2005 15:01	
GRAVUR	MPD	X	NCK-Dir.	25.11.2005 08:24	
SHOPMILL	MPD	X	NCK-Dir.	23.11.2005 14:30	
TEMP	MPD	X	NCK-Dir.	24.11.2005 15:29	
					Neu
					Um- benennen
					Markieren
					Kopieren
					Einfügen
					Aus- schneiden
					Weiteres
Freier Speicher					
Festplatte: 10 GBytes NC: 1273752					
NC					
Disk A					
USB					

4.2 Program Structure

By opening a directory, we can access existing programs, or we can set up new ones.

By pressing the arrow key



on the CNC keyboard, the selected directory opens.



In ShopMill, only main directories can be generated - mpf - and no subprograms - spf -.




After opening the directory, available programs are displayed in the directory. New programs can be created.

By pressing the softkey




new programs are generated that are managed in the opened directory.





Programming and program structure are described in the chapter Program Structure.

By pressing the arrow key,




the directory is closed. We are returned to the directory overview.



4.3 Editing Programs

The same functions are available as in MS Word.

With the softkeys below



directories, programs or individual program parts can be edited.

The individual softkeys are not described here in detail since they occur on the pages below in the exercises.


5 Saving Program Data

Here, all important program data, such as tools and zero points, can be stored.


By pressing the softkey




in the operating area



the softkey



appears in the vertical softkey bar. With “Save data”, the relevant machining data of the currently selected program can be saved.




By pressing this softkey,

a dialog field opens. With the key



the desired data is selected.



By pressing the softkey



an "ini" file is generated in the operating area



with the program name whose data was saved in the file.





The program with the corresponding "INI" file can now be saved externally.

With the program and the INI file, all relevant data for manufacturing a workpiece is saved and can be called any time.

When an "INI file" is selected, the stored data is read in again.

When the tools used in the program are read in, a query is displayed for tools with the same name: whether the current tool is to be overwritten.



Here, the "complete tool list" or the tools "used in the program" can be saved.


If the "complete tool list" is read in, all present tools are deleted, and replaced with those that were stored.

6 Program Structure - Milling


6.1 Program Header

The basic settings are described in the program header.

After entering the program name




and confirming the input with



the program header of the new program is opened automatically.

Here, the basic settings are made for the program sequence.




As the first input, a zero point shift for the program can be programmed directly in the program header.

NPV 1 G54


In the next input field, the raw part is defined.

As the first input field, the corner of the raw part is described.


Eckpunkt 1
X0 0.000 abs
Y0 0.000 abs
Z0 0.000 abs



Next, the raw part can be described either by means of the deviations in reference to the first corner




or the second corner of the raw part is described.



In the program header, only the raw part for simulation is defined. If no values for the raw part are entered, the milling center point path is displayed in the simulation.

In the next input fields, the following is defined: the tool axis, the return plane, and the safety distance.

Werkzeugachse	Z
Rückzugsebene:	
RP	10.000 abs
Sicherheitsabstand:	
SC	1.000 ink



A value for the safety distance has to be entered.

Regarding the machining rotational direction, we can select between synchronism

Gleichlauf

and reverse rotation

Gegenlauf



For the return motion, we can select between “return motion on the return plane”

auf RP

and


“return motion to safety distance”.

optimiert





For each machining, a return motion and a safety distance have to be specified.

The data entered in the program header can be redefined any time in the program by pressing the softkey




and Settings



7 Tool Management – Milling

In this module, the structure of tool management is described with its individual operating and setting options.

Content of the Module:




7.1 Calling the Tool List

After starting ShopMill, the operating area




is active.

By pressing the softkey



and Tools,






, in the area Tools





the Tool List

Werkzeugliste

Is called.



7.2 Structure of the Tool List



The Location Number:

The location number describes the magazine location. If there is a tool listed behind the location number, it is active; that is, it is present in the magazine.

Tools that don't have a location number are not active in the magazine. They are located in the "drawer", or in the manual magazine.




The Type:

Here, a symbol is assigned to the respective tool type.

P1.	Typ	Werkzeugname
		3D_TASTER
1		FAESER_10
2		PLANFRAESER83
3		BOHRER_10
4		GEWINDEBOHRER_12
5		ZENTRIERER_12
6		GESENKFR_ZYL
7		KUGELKOPFFR

The following tool types with their corresponding symbols are available:

8		FR_ECKENRADIUS
9		FRAESER_KEG
10		FR_KEG_ECKENRAD
11		GESENKFR_KEG
12		WINKELKOPF
13		KANTENTASTER

Typ	Werkzeugname
	FR_ECKENRADIUS

The Tool Name:

In this field, a name to identify the tool is entered.

Letters, numbers, and special characters can be entered.

DP
2

The Duplo Number:


If an additional tool is set up with a name that already exists, it becomes a duplo tool.

DP 1. Schneide		
Länge	s	
1	0.000	5.000
1	89.100	8.000

The Edge Length:

If a tool is measured, the tool lengths are provided in the tool list.

Ø
8.000



The Diameter:

Here, the tool diameter is entered into the list.

N
2

Number of Edges:

Here, the number of tool edges is entered.



The Spindle's Rotational Direction:

In the case of tools, the spindle's rotational direction refers to the tool spindle.

Right:



Left:



and spindle stop



Cooling Water Supply:

Under ShopMill, the inside as well as the outside coolant supply can be activated.

7.3 Tool Wear


In the area Tools

WERKZEUGE

-by pressing the softkey



- the input fields for Tool Wear




Werkzeugverschleiß

are activated

Here, the edge of a tool



can be assigned a wear value for the length and the diameter





The duration of tool operation can be defined by means of its service life

T Standzeit [min];

or the

C Stückzahl

number of units.



After reaching the prewarning limit, a message is displayed that the end of service life or the number of loads will soon be reached.

Tools can be defined as “blocked”

G

or as “oversize”.

U

2



BOHRER

8



FRAESER

7.4 The Magazine

7.5

In the area

WERKZEUGE

-by pressing the softkey



- the input fields for the

Magaz in

are activated.


Here, a magazine location can be blocked.

G

The tool status:


**Werkz .
zustand**

that is, when a tool is “blocked” or “oversize”, is displayed here.




Setting Up/Deleting a New Tool

As an example, the following tool will be set up.



In this case, the cursor has to be on a free input field of the *tool list*. By pressing the softkey



Neues Werkzeug

the different tool types are displayed in the vertical softkey bar. After selecting

Fräser

the name of the tool will be defined.

Schaftfraeser_20

Next, the diameter



20.000

as well as the number of teeth and the rotation direction are specified

3 2

The tool can now be measured in its length.



Example:



When machining with tools of the same type, unique names should be assigned, since duplo tools are generated from tools with the same name, without a warning.

To delete a tool from the tool list, select the location with the tool.

By pressing the softkey




the following softkeys are displayed:



By pressing the softkey



the selected tool is deleted from the tool list.



Take note of the machine manufacturer's data. In the case of some manufacturers, an active tool can not be deleted.

7.6 A Tool with Several Edges

A tool with several edges is set up as described above.

By pressing the softkey



the input screen form is displayed where several edges can be defined.

P1.	Typ	Werkzeugname	DP 1. Schneide	Länge	Ø	N	1	2
19	CUTTER10	1	0.000	10.000		4		
20	CUTTER6	1	0.000	6.000		3		
21								
22								
23	CENTERDRILL	1	0.000	12.000	90.0			
24								
25								
26	Schaftfraeser_20	1	0.000	20.000		3		

By pressing the softkey



an additional edge can be set up for the selected tool.

P1.	Typ	Werkzeugname	DP 1. Schneide	Länge	Ø	N	1	2
19	CUTTER10	1	0.000	10.000		4		
20	CUTTER6	1	0.000	6.000		3		
21								
22								
23	CENTERDRILL	1	0.000	12.000	90.0			
24								
25								
26	Schaftfraeser_20	1	0.000	20.000		3		

DP 2. Schneide


P1.	Typ	Werkzeugname	DP 2. Schneide	Länge	Ø
19	CUTTER10	1			
20	CUTTER6	1			
21					
22					
23	CENTERDRILL	1			
24					
25					
26	Schaftfraeser_20	1	0.000	0.000	

7.7 Sorting the Tools

When calling the tool list and pressing the softkey

Sortieren

the four options for sorting the tools are displayed.



The sorting that is active is shown darkend.

For sorting according to

nach Magazin

the tools are shown in the ascending mode according to their magazine location.

When sorting according to

nach Name

the tools are shown in the alphabetical order of the name.

WERKZEUGE

Werkzeugliste

19

20

21

22

23

24

25

26

P1.	Typ	Werkzeugname	DP 1.	Schneide					
				Länge	Ø		N	1	2
19		CUTTER10	1	0.000	10.000		4		
20		CUTTERS	1	0.000	6.000		3		
21									
22									
23		CENTERDRILL	1	0.000	12.000	90.0			
24									
25									
26		Schaftfraeser_20	1	0.000	20.000		3		

Werkz. liste

Werkz. versch

Maga-zin

Nullp. versch

R

R-Para-meter

Alternat.

Werkzeug messen

Werkzeug löschen

Entladen

Schneide

Sortieren

WERKZEUGE

Werkzeugliste

P1. Typ Werkzeugname

DP 2. Schneide

Länge

Ø

19		CUTTER10	1		
20		CUTTERS	1		
21					
22					
23		CENTERDRILL	1		
24					
25					
26		Schaftfraeser_20	1	0.000	0.000

nach
Magazin

nach
Name

nach
Typ

nach
T-Nummer

«
Zurück

Werkz.
liste

Werkz.
versch

Mag-
zin

Nullp.
versch

R-Para-
meter

1		FAESER_10
2		PLANFRAESER83
3		BOHRER_10
4		GEWINDEBOHRER_12

1		FAESER_10
		FRAESER10
16		FRAESER16
		FRAESER20

When sorting



27		Kugel
6		GESENKFR_ZYL
7		KUGELKOPFFR

the tools are sorted according to the tool type.

When sorting



123
1234
12345

tool names that are defined by numbers are sorted in the ascending mode.


8 Programming Example: Contour Programming

The contour calculator and subsequent machining are described, based on an example.

8.1 Example of Contour Programming

A ShopMill program is to be created for this workpiece.

After setting up a program with the name "Mounting Plate",



the inputs are made in the program header.


NPV	1	G54	mm
Rohteil:			
Eckpunkt 1			
X0	0.000	abs	
Y0	0.000	abs	
Z0	2.000	abs	
Abmaße			
L	150.000		
W	100.000		
H	-20.000		
Werkzeugachse Z			
Rückzugsebene:			
RP	80.000	abs	
Sicherheitsabstand:			
SC	1.000	ink	
Bearbeitungsdrehsinn:			
Gleichlauf			
Rückzug Pos.-muster:			
optimiert			

PROGRAMM		SPRITZFORM	
P	END	<div> </div>	
<div> Programmkopf NPV 1 G54 mm Rohteil: Eckpunkt 1 X0 0.000 abs Y0 0.000 abs Z0 2.000 abs Abmaße L 150.000 W 100.000 H -20.000 Werkzeugachse Z Rückzugsebene: RP 80.000 abs Sicherheitsabstand: SC 1.000 ink Bearbeitungsdrehsinn: Gleichlauf Rückzug Pos.-muster: optimiert </div>		<div> Alternat. Nullpunkt versch. Abbruch Übernahme </div>	
<div> Gerade Kreis Bohren Fräsen Kontur fräsen Diverses Simulation Abarbeiten </div>			

8.2 Face Milling

The workpiece surface is milled in order to obtain a level, clean surface. This is done with face milling.


After accepting the program header,




face milling is performed next.

After entering the values in the input screen form,

T	PLANFRAESER83	D1
F	0.200 mm/Zahn	
V	190 m/min	
Bearbeitung:	▽	
Richtung:	↑↑↑	
X0	0.000 abs	
Y0	0.000 abs	
Z0	2.000 abs	
X1	150.000 ink	
Y1	100.000 ink	
Z1	0.000 abs	
DXY	40.000 %	
DZ	2.000	
UZ	0.000	




face milling is accepted into the machining plan.





8.3 Contour Calculator

With the contour calculator, even difficult contours can be programmed relatively easily.

Next, the milling contour is described.





After setting up a new contour,




the starting point is defined in the contour calculator.

X 5.000 abs
Y 5.000 abs


Then, the first contour element is programmed.




X 9.895 abs
Y 75.000 abs
 α_1 86.000 °



When entering the angle, the direction has to be noted.



Next, the arc is programmed



After entering the values


Drehrichtung:

R


X

Y

a dialog selection is displayed.




By pressing the softkey





the selected element is accepted into the contour calculator.

The direction of the element selected in the dialog can be changed any time by pressing the softkey




The next element is a straight line in X direction.




X 120.000 abs
α2 2.111°
Übergang zum Folgeelement:
R 0.000

Then, an arc follows again.




For this element also, a dialog selection is made which is accepted into the contour calculator by pressing the softkey




**Dialog
Übernahme**



The next element is an oblique line whose end point is known.



X 145.000 abs
Y 5.000 abs
 $\alpha 1$ -85.914 °
 $\alpha 2$ 4.086 °



With the last contour element, a straight line, the contour is closed.



By pressing the softkey Additional

Weiteres

and Close Contour

Kontur schließen

the contour is completely generated.

8.4 Path Milling

After accepting the contour in the machining plan

 N15 AUSSEN



a bracket opens next to the symbol for the contour element.

Next, the machining process is described. Path milling is to be used for machining.

By pressing the softkey



In the area “**Contour milling**”, a corresponding input screen form is opened.




8.5 Forward-Backward

We can also machine against the programmed contour (backward).

After entering the tool,
the technology and
selecting the radius
correction

T **FRAESER20** D1
F 0.200 mm/Zahn
V 100 m/min
Radiuskorrektur:

we can then specify
the machining
direction in reference
to the contour.



vorwärts

The contour is
processed in the
direction the contour
was programmed.


rückwärts

The contour is processed
against the contour's
programmed direction. After
entering the machining
strategy,

Bearbeitung:
Z0 0.000 abs
Z1 10.000 ink
DZ 5.000
UZ 0.000
UXY 0.000 mm

the **approach and
the return strategy
as well as the
retraction mode** are
defined.


Anfahren: Gerade
L1 2.000
FZ 0.200 mm/Zahn
Abfahren: Gerade
L2 2.000
Abhebemodus:
auf Rückzugsebene




Accepting the machining into the machining plan



closes the bracket. A machining was added to the contour.



The program is done.




9 Programming Example Contour Spigot

Content of this module:

This module describes the standard milling cycle Contour Spigot, using an example. The contour remains, and the residual material is milled off.


9.1 Contour Spigot Milling – Removing Residual Material

This example is programmed using ShopMill.




This is not possible with the path milling cycle, since as a maximum, a 10 milling tool can be used.




Residual corners remain.



For this reason, two contours have to be described: one that surrounds the raw part, the so-called "limit contour" and the actual contour that jumps out; that is remains as an "island".



After setting up a new program



After setting up a new program



and making the inputs in the program header

Programmkopf

NPV **1** **G54** mm

Rohteil:
Eckpunkt 1


X0 0.000 abs
Y0 0.000 abs
Z0 2.000 abs

Abmaße


L 120.000
W 60.000
H -10.000

Werkzeugachse **Z**

Rückzugsebene:
RP 80.000 abs
Sicherheitsabstand:
SC 1.000 ink
Bearbeitungsdrehsinn:
Gleichlauf
Rückzug Pos.-muster:
optimiert




face-milling the
workpiece surface,




a new contour is set
up <<same page twice?>>.

9.3 First Contour Limit-Contour



This contour, a little larger than the workpiece, will later describe the machining limit.


The initial machining continues to be done with the facing tool.





In the case of spigot milling, the “limit contour” can be angular. When describing a contour pocket, the contour corners should have a radius. The corner radius should be at least as large as the radius of the largest tool.

9.4 Second Contour: Actual Contour Spigots


Next, a second contour is programmed.



After accepting the contour in the machining plan, the cycle for contour spigot milling is opened by pressing the softkey




The strategy is that we always start outside of the workpiece when starting machining.



By machining from the outside to the inside, tough and hard materials can also be machined in this cycle.



Then, the values are entered.

Zapfen Fräsen	
T	FRAESER_30 D1
F	0.200 mm/Zahn
V	120 m/min
Bearbeitung: ▾	
Z0	0.000 abs
Z1	5.000 ink
DXY	40.000 %
DZ	5.000
UXY	0.000 mm
UZ	0.000
Abhebemodus: auf Rückzugsebene	





9.5 Spigot – Residual Material

The values that were entered are accepted into the machining plan. Thus, the bracket with the two contour elements is closed.



Since based on the milling tool diameter of 30mm the workpiece can not be completely manufactured, another machining cycle follows; so-called "residual material processing".

Pressing the softkey






opens the cycle for residual material machining.
After selecting a smaller milling tool and inputting the values,

Zapfen Restmaterial		
T	Schafttraeser_16	D1
F	0.200 mm/Zahn	
V	120 m/min	
Bearbeitung: ▾		
DXV	2.000 mm	
DZ	2.000	
Abhebemodus: auf Rückzugsebene		

this cycle is accepted into the machining plan.
This cycle is added to the bracket.

~	N15 GRENZE
~	N20 FORM
⊞	N25 Zapfen Fräsen
⊞	N30 Zapfen Restmat.

The program is done.





10 Programming Example Standard Milling Cycles


Machining with the standard milling cycles under ShopMill is described, using an example

10.1 Programming Example for Milling Cycles (Rectangular Spigot, Circular Pocket)



This workpiece
"Mounting Plate " is to
be generated using
the milling cycles



After setting up a
program named
"Mounting Plate"





the raw part for the
simulation is entered,
after entering the zero
point.




After entering the
additional values in
the program header

and accepting them into the machining plan,


the next step consists of facing.



Pressing the softkeys




and



10.2 Face Milling

opens the input screen form for face milling.

Using the four vertical softkeys






machining limits can be defined.

Example:
Activated limits



We don't have to define a machining limit in this example. After selecting the tool and the technological data,




Planfräsen		
T	PLANFRAESER83	D1
F	0.200 mm/Zahn	
V	190 m/min	

next Roughing,











or Finishing




is selected.


Then, we select the machining strategy.



After entering the values, face milling is accepted into the machining plan




by pressing the softkey




10.3 Rectangular Spigot

Next, the rectangular spigot is programmed.





Pressing the softkey



in the area Milling and selecting



opens the input field.




After selecting the tool with the corresponding technology,


T	FRAESER32	D1
F	0.200 mm/Zahn	
V	120 m/min	

next the reference point of the rectangular spigot is defined.


Mitte




unten links




unten rechts



oben links



oben rechts




After selecting the position

Mitte

the spigot and the machining strategy are described.


Mitte	
Bearbeitung:	▼
Einzelposition	
X0	0.000 abs
Y0	0.000 abs
Z0	0.000 abs
W	75.000
L	75.000
R	0.000
$\alpha 0$	0.000 °
Z1	10.000 ink
DZ	3.000
UXY	0.000 mm
UZ	0.000



Finally, the raw part spigot is specified that is to be machined.

W1	101.000
L1	101.000


The spigot is programmed.




The material between the raw part spigot and the finished part spigot is machined in a lateral feed setting.
If the feed setting is too large, the completed spigot should be programmed in several steps.

10.4 Circular Pocket

Finally, the circular pocket is programmed.



By selecting the cycle “circular pocket“, the corresponding input field opens. After selecting the tool and entering the technology data



T **FRAESER20** D1
F 0.200 mm/Zahn
V 80 m/min

the circular pocket is programmed.


Bearbeitung: (dropdown menu)
Einzelposition
X0 0.000 abs
Y0 0.000 abs
Z0 0.000 abs
s 50.000
Z1 26.000 ink
DXY 40.000 %
DZ 5.000
UXY 0.000 mm
UZ 0.000

Immersion in the material can be centered

Eintauchen: **mittig**
FZ 0.100 mm/Zahn

or helical.


Eintauchen: **helikal**
EP 2.000 mm/U
ER 4.000 mm




G_NC01_de_00099

For **helical** immersion, a Z-motion is superimposed on the X-Y motion. The milling tool backs off permanently because of this.

Accepting the cycle into the machining plan completes the program



and can be simulated.



10.5 Processing (Basic Block)

By pressing the softkey



the program is loaded to the operating mode





and can be processed.

Pressing the softkey



displays the program during processing in an additional window in **G-code**.



By activating the basic block, the next programmed travel movements are visible.
This makes a possible early intervention in program execution simpler for the operator.


11 Programming Example – Position Patterns for Drilling and Milling Cycles

Below, the position patterns for drilling and milling cycles under ShopMill are explained, using an example.

11.1 Example: Drilling and Milling Positions

A rectangle and the circular pockets are added to the example for contour programming.

The program “Injection Mold” is selected in the area



VERZEICHNIS

Pressing the softkeys

Kopieren

and

Einfügen

opens a dialog window.

Programm/Verzeichnis überschreiben

SPRITZFORM

Datei bereits vorhanden!
Überschreiben?

SPRITZFORM

VERZEICHNIS

Name	Typ	Geladen	Größe	Datum/Zeit
SHOPMILL.WPD...				
FORM_TMZ	INI		1933	05.05.2006 15:10
FORM	MPF	X	1957	08.05.2006 09:49
MONTAGEPLATTE	MPF	X	499	09.05.2006 10:56
SPRITZFORM	MPF	X	1044	05.05.2006 11:36

Programm/Verzeichnis überschreiben

SPRITZFORM

Datei bereits vorhanden!
Überschreiben?

SPRITZFORM


Freier Speicher Festplatte: 10 GBytes NC: 1269656

NC Disk A Test USB


Abbruch OK

Since the existing program is not to be overwritten, a 2 is appended to the name of the program.

By pressing the softkey




a new program named "InjectionMold2" is stored in the selected directory.




11.2 Rectangular Pocket

After opening the program, the corresponding cycle for machining the center pocket is called by pressing the softkey





and




After entering the corresponding values in the input screen form

Rechtecktasche	
T	FRAESER10 D1
F	0.100 mm/Zahn
V	111 m/min
Mitte	
Bearbeitung: ▾	
Einzelposition	
X0	75.000 abs
Y0	50.000 abs
Z0	0.000 abs
W	40.000
L	60.000
R	6.000
α0	30.000 °
Z1	15.000 ink
DXY	40.000 %
DZ	5.000
UXY	0.000 mm
UZ	0.000
Eintauchen:	mittig
FZ	0.100 mm/Zahn
Ausräumen: Komplettb.	

and acceptance into the machining plan,


the rectangular pocket is programmed.




If necessary, any number of position patterns can be described one after the other.

11.3 Circular Pockets


Next, the circular pockets are programmed.



After opening the corresponding cycle



and <<something missing?>>, the tool with the corresponding technology is entered.



11.4 Position Pattern

Now, not the
Individual Position

Einzelposition

as previously, but
-since it is a question
of several circular
pockets of the same
type- by pressing the
softkey



the

Positionsmuster

is selected.
Based on this
selection,

T	FRAESER20	D1
F	0.200 mm/Zahn	
V	80 m/min	
Bearbeitung:		
	Positionsmuster	
Ø	50.000	

it is no longer
possible to describe
positions in the input
screen form of the
cycle.

Input of values in the
screen form.

Ø	30.000
Z1	10.000 ink
DXV	40.000 %
DZ	5.000
UXV	0.000 mm
UZ	0.000
Eintauchen:	helikal
EP	2.000 mm/U
ER	4.000 mm
Ausräumen:	Komplettb.

11.5 Drilling and Positions

Through acceptance into the machining plan, an open bracket is displayed at the circular pocket.



Next, the positions of the circular pockets are programmed.

Pressing the softkey





and



opens the corresponding input field.

As an alternative, the circular pocket positions can also be entered with the position pattern “Frame”.




After entering the corresponding positions in the input screen form

rechtwinklig	
Z0	0.000 abs
X0	30.000 abs
Y0	25.000 abs
X1	30.000 abs
Y1	75.000 abs
X2	120.000 abs
Y2	75.000 abs
X3	120.000 abs
Y3	25.000 abs

and acceptance into the machining plan, the bracket is closed and the program is complete.

N30 Kreistasche
N35 001: Positionen




12 Program Example – Centering, Drilling, Threading

In this module, centering, drilling and threading under ShopMill is described.


12.1 Exercises for Centering, Drilling, and Threading

As an example for centering, drilling and threading, this drawing is to be programmed.


After setting up a new program.






defining the program header,



and programming the face milling cycle,



the next step consists of programming the centering.




12.2 Centering the Frame and the Hole Circle

After opening the input screen form for the centerings (spot drilling), the values are entered in the input fields.


T	ZENTRIERER_12	D1
F	0.200 mm/min	
S	1000 U/min	
Spitze		
Z1	3.000 ink	
DT	0.000 s	


Since at none of the holes a chamfer is programmed, centering can be done for all holes.



The positions of the center circle


Vollkreis	
Z0	0.000 abs
X0	0.000 abs
Y0	0.000 abs
α0	0.000 °
R	20.000
N	6
positionieren: Gerade	






as well as the outside frame are programmed.

Rahmen	
Z0	0.000 abs
X0	-60.000 abs
Y0	-40.000 abs
α0	0.000 °
αX	0.000 °
αY	0.000 °
L1	60.000
L2	40.000
N1	3
N2	3




12.3 Drilling

After accepting the position patterns into the machining plan, the centerings for the holes are completely programmed.



Next, the holes for the center hole circle are programmed.





12.4 Programming "Drilling the Hole Circle" by Using Copy and Insert

After opening the input screen form for drilling and entering the values,



Bohren	
T	BOHRER_6 D1
F	0.200 mm/min
V	100 m/min
Spitze	
Z1	25.000 ink
DT	5.000 s

the input is accepted into the machining plan.



Since the drilling positions were already programmed, they are appended to the boring by pressing the softkeys



and




The center borings are completely generated.



12.5 Borings Threads for Frames

Finally, the borings of the “frame” are programmed.

After entering the values for the borings



Bohren		
T	BOHRER_8.6	D1
F	0.200 mm/min	
V	100 m/min	
Schaft		
Z1	35.000 ink	
DT	0.000 s	

and entering the values for the thread,

PROGRAMM		Verweilzeit in Sekunden			
GEHÄUSEPLATTE					
Bohren		Bohren		Alternat.	
T	BOHRER_8.6	D1		Werkzeuge	
F	0.200 mm/min			Bohren	
V	100 m/min			Reiben	
Schaft					
Z1	35.000 ink			Abbruch	
DT	0.000 s			Übernahme	
<div>Gerade Kreis Bohren Fräsen Kontur fräsen Diverses Simulation Abarbeiten</div>					

Gewindebohren		
T	GEWINDEBOHRER-M10 D1	
P	1.500 mm/U	
V	20 m/min	
VR	16 m/min	
Spänebrechen		
Z1	30.000 ink	
D	5.000	
V2	automatisch	

PROGRAMM		1 Schnitt/Entspannen/Spänebrechen			
GEHÄUSEPLATTE					
Gewindebohren		Gewindebohren		Alternat.	
T	GEWINDEBOHRER-M10 D1			Werkzeuge	
P	1.500 mm/U			Gewindebohren	
V	20 m/min			Gewindefräsen	
VR	16 m/min			Bohrge- fräsen	
Spänebrechen					
Z1	30.000 ink			Abbruch	
D	5.000			Übernahme	
V2	automatisch				
<div>Gerade Kreis Bohren Fräsen Kontur fräsen Diverses Simulation Abarbeiten</div>					

the inputs are accepted into the machining plan.






Since the positions for the borings were already programmed also, they are again appended to the boring by pressing the softkeys



and




The program is completely generated.



13 Programming Example – Programmable Transformations, Subprogram Technology


Content of the Module:

This module describes how ShopMill transformations and subprograms are programmed, using an example.




Mirroring/rotating transformations

Based on this example, the functions “Program Loop” - “Shift” are explained in greater detail..



All non-dimensioned radii R=5

Setting up the program



13.1 Program Header

After entering the values in the program header

Programmkopf

NPV 1 G54 mm

Rohteil:
Eckpunkt 1

X0 -75.000 abs
Y0 -50.000 abs
Z0 2.000 abs

Abmaße

L 150.000
W 100.000
H -20.000

Werkzeugachse Z

Rückzugsebene:
RP 80.000 abs
Sicherheitsabstand:
SC 1.000 ink
Bearbeitungsdrehsinn:
Gleichlauf
Rückzug Pos.-muster:
optimiert

and entering the parameters for face milling,

Planfräsen

T PLANFRAESER83 D1




F 0.200 mm/Zahn
V 190 m/min

Bearbeitung:

Richtung:

X0 -75.000 abs
Y0 -50.000 abs
Z0 2.000 abs
X1 150.000 ink
Y1 100.000 ink
Z1 0.000 abs
DXY 40.000 %
DZ 2.000
UZ 0.000


next the corner contour is programmed.



13.2 Contour Calculator Left Upper Corner


After opening the contour calculator and defining the starting point for the left upper corner,

Startpunkt	
Werkzeugachse	Z
X	-75.000 abs
Y	32.000 abs




the contour is programmed incrementally.

Gerade X	
X	18.000 ink
Übergang zum Folgeele.: R	10.000




Gerade Y	
Y	18.000 ink
α2	90.000 °
Übergang zum Folgeele.: R	0.000




13.3 Path Milling



After accepting the contour into the machining plan,



the cycle “Path Milling” is opened.



After accepting the values into the machining plan, corner machining is programmed.



13.4 Mirroring

We don't want to program this corner three more times, but mirror it under ShopMill.

After pressing the soft key






and



the possible transformations under ShopMill are shown.



Pressing the softkey Mirroring




opens the corresponding input screen form.


The corners are mirrored “additively”; that is, always in reference to the reference point that was mirrored last.

After activating the corresponding axis


Spiegelung	
	additiv
X	ein
Y	aus
Z	aus






and accepting it into the machining plan, all additional program steps are inserted behind the mirror image around the X-axis.



After highlighting and copying the contour with the associated processing of Copy





the contour is inserted behind the mirror image by pressing the softkey




Copied program parts are inserted below the current position.


The second corner
has been
programmed



With another additive
mirroring -this time
around theY-axis-





and subsequent
additive mirroring
around the X-axis,



and additionally
inserting the contour
including the
processing below the
mirrorings

13.5 Longitudinal Grooves

the program for the 4 corner machinings is completed






After entering the last corner, mirroring is still active and has to be switched off with



Next, the longitudinal grooves on both sides are milled.

After opening the cycle for longitudinal grooves and entering the corresponding values in the input screen form,







the cycle is accepted into the machining plan.

After opening the input screen form for the position pattern, entering the corresponding values

rechtwinklig	
Z0	0.000 abs
X0	-66.000 abs
Y0	0.000 abs
X1	66.000 abs
Y1	0.000 abs

and acceptance into the machining plan,


the longitudinal grooves are completely programmed.



13.6 Circumferential Groove

Next, the circumferential grooves are programmed.

After opening the cycle for circumferential grooves and entering the corresponding values in the input screen form,



Kreisnut

T **FRAESER_8** D1

F 0.200 mm/Zahn

FZ 0.200 mm/Zahn

V 89 m/min

Bearbeitung: ▾

Vollkreis

X0 0.000 abs

Y0 0.000 abs

Z0 0.000 abs

W 8.000

R 52.000

α0 140.000 °

α1 80.000 °

N 2

Z1 5.000 ink

DZ 5.000

UXY 0.000 mm

positionieren: Gerade

PROGRAMM

FORMPLATTE

Werkzeugname

Kreisnut

T **FRAESER_8** D1

F 0.200 mm/Zahn

FZ 0.200 mm/Zahn

V 89 m/min

Bearbeitung: ▾

Vollkreis

X0 0.000 abs

Y0 0.000 abs

Z0 0.000 abs

W 8.000

R 52.000

α0 140.000 °

α1 80.000 °

N 2

Z1 5.000 ink

DZ 5.000

UXY 0.000 mm


positionieren: Gerade

Übernahme

Gerade Kreis Bohren Fräsen Konturfräsen Diverses Simulation Abarbeiten

the cycle is accepted into the machining plan.

The circumferential grooves are completely programmed.



PROGRAMM

FORMPLATTE

N10 Planfräsen ▾ T=PLANFRAESER83 F0.2/Z V190m X0=-75 Markieren

N15 ECKE

N20 Bahnfräsen ▾ T=FRAESER20 F0.2/Z V100m Z0=0 Z1=10ink Kopieren

N25 Spiegelung add X

N30 ECKE

N35 Bahnfräsen ▾ T=FRAESER20 F0.2/Z V100m Z0=0 Z1=10ink Einfügen

N40 Spiegelung add Y

N45 ECKE

N50 Bahnfräsen ▾ T=FRAESER20 F0.2/Z V100m Z0=0 Z1=10ink Aus-schneiden

N65 Spiegelung aus

N85 ECKE

N90 Bahnfräsen ▾ T=FRAESER20 F0.2/Z V100m Z0=0 Z1=10ink Suchen

N95 Längsnut ▾ T=FRAESER_8 F0.2/Z V170m Z1=5ink W8 L54

N115 001: Positionen Z0=0 X0=-66 Y0=0 X1=66 Y1=0

N125 Kreisnut ▾ T=FRAESER_8 F0.2/Z V89m X0=0 Y0=0 Z0=0

END Programmende N=1


Übernahme

Gerade Kreis Bohren Fräsen Konturfräsen Diverses Simulation Abarbeiten


13.7 Contour Pockets with Contour Calculator

Next, the contour pockets are programmed.


After opening the contour calculator, that pocket's starting point is defined.




X 0.000 abs
Y 42.000 abs



Then, half the arc is programmed.




By pressing the
softkey



additional input
options are available.


The angle of opening
that was dimensioned
in this way is entered
in the extended input
screen form.

Kreis	
Drehrichtung:	<input type="text" value="R"/>
R	42.000
X	-34.404 abs
X	-34.404 ink
Y	24.090 abs
Y	-17.910 ink
I	0.000 abs
I	0.000 ink
J	0.000 abs
J	-42.000 ink
α1	180.000 °
β1	235.000 °
β2	55.000 °
Übergang zum Folgeele.:	R
R	5.000





Then, the oblique line is programmed.

After opening the input screen form and pressing the softkey



**Alle
Parameter**

the length of the oblique line as well as the angle to the predecessor element is entered.





Next, the lower arc is programmed.

After opening the input screen form and pressing the softkey

**Alle
Parameter**

the arc is programmed again by means of the angle of opening.






Now the oblique line is programmed again.


After opening the input screen form and pressing the softkey

Alle Parameter

the length of the oblique line as well as the angle to the predecessor element is entered.





With the last element, the contour is closed.



14 Rotation Contour Pockets

After accepting the contour into the machining plan and adding the processing “Contour pocket”, the first pocket is completely programmed.






By pressing the softkey




in the area “Diverses“, the contour pocket is rotated around the Z-axis.



After entering the rotation





and copying and inserting the contour with the processing below the rotation, the second contour pocket is complete.



The last contour pocket is generated in the same way.




Delete the rotation



15 Making Holes with a Drill


As the last step, the holes are programmed.




After entering the values

Verweilzeit in Sekunden	
Bohren	
T	VOLLBOHRER_10 D1
F	0.120 mm/U
S	1200 U/min
Spitze	
Z1	10.500 ink
DT	0.000 s


and the positions



rechtwinklig/polar	
Positionen	
rechtwinklig	
Z0	-21.000 abs
X0	-66.000 abs
Y0	41.000 abs
X1	66.000 abs
Y1	41.000 abs
X2	66.000 abs
Y2	-41.000 abs
X3	-66.000 abs
Y3	-41.000 abs
X4	abs
Y4	abs
X5	abs
Y5	abs
X6	abs
Y6	abs
X7	abs
Y7	abs
X8	abs
Y8	abs




the program is
complete.





16 Subprograms

In this program, subprograms are inserted as repetitions. To make the program more transparent, the contour pockets are moved to a subprogram.



by cutting out the contour pockets from the program "Pattern Plate" and inserting them into the new program "Contour Pocket".

Then, the program is complete.




Now, the program has to be simulated once. This action calculates the program, and can be used as a subprogram .

By pressing the softkey



in the area "Diverses"





the name of the subprogram is entered.

Unterprogramm
Pfad/Werkstück:
Programmname:
Konturtasche

If the subprogram is located in the same path, no input is necessary under Path/Workpiece.

The program name is entered without an extension such as *mpf* and accepted into the machining plan.

The subprogram is complete.




Any main program can also be used as subprogram!

17 Mould Making - Milling

A mould making program is generated, using an example.

Sequence



17.1 Prerequisites

In addition to machining step programs, ShopMill can also process G-code mould making programs.
The prerequisite for this are optimized drives.

Program Structure

In order to attain the optimum velocity control for the mould making programs, you should divide the mould making program into a central technology program and separate geometry programs, and not generate one complete program.

Technology Program

The technology program includes the basic settings such as zero point shift, tool calls, feed values, spindle speed, and control commands for velocity control.


In addition, the technology program calls the geometry programs as subprograms.

The technology program can be generated in the ShopMill's G-code editor..

Geometry Program

The geometry programs of the individual machining modes (roughing, prefinishing and finishing) exclusively contain the geometry values for the free form surface to be machined. The geometry programs are generated on an external CAM system in the form of G01 blocks. Depending on their application, the geometry programs have a size of 500KB up to 100MB. Programs of this size can no longer be processed directly in the NCK work memory, but have to be processed externally by means of EXTCALL. That means, the geometry programs have to be stored either on the hard drive of the PCU 50.3 (HMI Advanced) or on a Compact Flash Card at ShopMill on NCU (HMI Embedded). For both ShopMill variants you also have the option to store the geometry programs on a network drive.

17.2 Program Structure Technology Program with Geometry Program




Complete Program

Complete programs include the basic settings such as the zero point shift, tool function <<T word>> etc. as well as the geometry values of the free form surface to be machined. However, programming the optimized velocity control for a complete program is very complicated.

Complete programs are also generated on external CAM systems. Because of their size, the complete programs are located on the hard drive of the PCU 50.3 (HMI Advanced) or on the CompactFlash Card at ShopMill on the NCU (HMI Embedded).

Here also you have the option to store the complete programs on a network drive.

17.3 Program Structure Complete Program



Data Transmission

A mould making program can be copied directly to the controller from a network drive or a USB drive.

- ShopMill on NCU (HMI Embedded)
- The programs are copied to the user memory of the CompactFlash card.
- PCU 50.3 (HMI Advanced)

The programs are copied to the hard disk drive.

Measuring the Tool

When generating the geometry program, the CAM system takes the tool geometry into account. The calculated tool path refers either to the tool tip or the tool center point. That means, when you specify the length of your tools, you have to use the same reference point (tool tip or tool center point) as the CAM system.

If you are using a ShopMill function for measuring your tools, the tool length refers to the tool tip. If, on the other hand, in the CAM system the tool center point was taken into account when calculating the tool path, you have to deduct in the tool list the radius of the tool from the length of the tool. To process mould making programs, the entry of the tool diameter in the tool list is not relevant. However, to have a better overview, you should enter the tool diameter in the tool list nevertheless.

17.4 Creating the Program

Setting Up the Program

For the technology program, set up a new G-code program in the program manager and then edit it there.

Editor. *A machining step program is not suitable as a technology program.*


Create the geometry program or the complete program with an external CAM system. If afterwards you would like to add comments, for example, to the geometry program, or change the tool name in the complete program, you can use also the ShopMill G-code editor for this.



Use the arrow keys to open a directory.



After entering a program name,






the G-code Editor under ShopMill is opened.

Programming the Tool

If you program a tool in the technology program, you have to take note of the following:

The geometry of the programmed tool has to agree with the tool geometry that the CAM system took into account when the geometry program was generated.

First, the tool, the spindle speed and the spindle direction are programmed. In addition, the following is programmed: feed, switching on the coolant, and the zero point shift with the starting point.




17.5 High Speed Settings

Programming the Cycle "High Speed Settings"

When machining free form surfaces, great demands are made on the speed as well as the accuracy and surface quality. You can attain the optimum velocity rate in dependence on the machining mode (roughing, pre-finishing, finishing) very simply by using the cycle "High Speed Settings". You can call the cycle by means of the cycle support in the G-code editor. As a rule, the output tolerance of the post processor of the CAM system is entered in the parameter "Tolerance". Program the cycle in the technology program prior to calling the geometry program.

After pressing the softkeys




High speed settings

the following input screen form opens, where we can select among the machining modes

Schlichten


Vorschlichten

Schruppen



Tolerance

The required tolerance can be entered in the input screen form in the cycle for the program generated from the CAM system.



If the compressor is active, it can be parameterized by means of the input screen form.


By pressing the softkey

Alter-nativ

we can select between

COMPCAD

COMPCURV



By pressing the softkey


Alter-nativ

we can select among

FFWOF SOFT

FFWON SOFT

FFWOF BRISK




Pressing the
softkey



closes the input
screen form.

“CYCLE832” was
accepted into the
program.



17.6 Calling the Subprogram

Call the geometry program as subprogram from the technology program. Since the geometry programs are not stored in the NC work memory but on the hard disk drive of the PCU 50.3, or on the Compact Flash Card of the TCU, or on a network, the subprogram has to be called with the G-code command "EXTCALL".

PCU 50.3

The technology program and the geometry programs are located in the same directory on the hard disk drive.

EXTCALL "Geometry program"

Example: EXTCALL "SCHRUPPEN"

<<ROUGHING>>

NCU HMI Embedded

Depending on the storage location of the geometry program on the Compact Flash Card, the programming syntax differs somewhat.

- The geometry program is located directly on the Compact Flash Card

EXTCALL ("C:\Geometrieprogramm.mpf")

Example: EXTCALL ("C:\Schruppen.mpf")

- The geometry program is located in a directory on the Compact Flash Card

EXTCALL

("C:\Verzeichnis\Geometrieprogramm.mpf")

Example: EXTCALL ("C:\Mold\Schruppen.mpf")


Network drive

If the geometry program is located on a network drive connected by means of the Ethernet, the programming syntax is as follows.

EXTCALL ("Pfad\Geometrieprogramm.mpf")

Example: EXTCALL ("H:\Mold\Schruppen.mpf")

Here, a program is called that is stored on the CFCard as mpf– program.





17.7 Processing the Program

Select the technology program that is located in the NCK work memory like a standard G-code program for processing. The geometry program is then selected automatically with the command "EXTCALL".

A complete program that is located either on the hard disk drive of the PCU 50.3 (HMI Advanced), or on the Compact Flash Card at ShopMill on NCU (HMI Embedded), or on a USB /network drive, is selected with the softkey "Execute hard drive" in the program manager.

Prior to executing the program, the program is simulated graphically by pressing the softkey




Pressing the softkey




and



the program is selected in the operating area “Auto”.




The program can be executed in the single block.



With “Cycle Start” the program can be executed step by step.



After positioning, the program can be executed without a single block.



17.8 Starting Processing at a Certain Program Location

Executing the Program

Starting Processing at a Certain Program Location

In order to start in a geometry program the execution of a certain program segment, enter the destination in the search pointer.

Layer 1 (technology program):

Program line with the call of the desired geometry program

Layer 2 (geometry program):

Program line for starting processing.

If the geometry program is located on the Compact Flash Card, you not only have to specify in Layer 2 in the input field

"Program" the program name, but also the path.


Select the accelerated calculation variant

"External – without calculation". The block search in the technology program is performed with calculation. In that case, all EXTCALL commands before the desired geometry program are skipped. The block search in the desired geometry program is performed without calculation. However, this calculation variant presupposes that all machine functions such as tool function, spindle speed etc. are located in the technology program. The geometry program must only contain geometry values for the free mold surface.

The line for starting the program can be selected with the arrow keys.



After pressing the two additional softkeys




the selected program block is active.

By then pressing the key




the message 10208
Channel 1 for
continuing the
program appears.
Press NC Start



If we want to start
from a certain
program point,
the program is started by
pressing



and




and entering the
program number

and pressing the
softkey




Sample Program


In the program area “NC”, a mould making program is opened.



The corresponding technology data is located on the “CF Card”. With a mouse click, it was loaded to the “CF Card” with a USB stick.




17.9 Simulation of a Volume Model




18 Information about Mould Making

Information about mould making is provided on the Internet under
www.automation.siemens.com/doconweb/




The difference between a manual and a CNC machine consists of the logic operation of numerical values. This module about the basics of CNC technology is to aid you regarding the CNC myth.





20 Manual Operating Area - Milling


In this module, the individual function areas in the manual operating area are presented and if necessary, explained by using an example.



Tool Spindle Speed Machine Functions

 T, S, M

T		D
Spindel		U/min
Spindel M-Fkt.		
Sonst. M-Fkt.		
Nullpktv.		
Maßeinheit		
Werkzeugachse		



In the first input screen form, the tool is defined.

T D

The spindle speed can be entered only in

U/min

In the additional input fields, M-functions and zero point shifts can be input.

Sonst. M-Fkt.
Nullpktv.

We can select between the measurement units

mm


in

The tool axis

Werkzeugachse

can also be selected.

Example:



After calling the tool with the corresponding technology

T Schaftfräser_20 D1
Spindel 1200 U/min
Spindel M-Fkt. 2

the tool with the input technology data is activated by pressing the NC start key



MANUELL		Reset		Alternat.	
WKS	Position [mm]	T,F,S			
X	150.000	T		↓ Z	
Y	150.000	F	0.000 100% mm/U		
Z	0.000	S	0.000 0%		
T,S,M...		rechts/links/aus/positionieren			
T Schaftfräser_20 D1					
Spindel 1200 U/min					
Spindel M-Fkt. 2					
Sonst. M-Fkt.					
Nullpktv.					
Maßeinheit					
Werkzeugachse					
		Zurück			

T,F,S	
T KUGEL_6 D1	↓ Z
Ø 6.000	
F	0.000 100% mm/U
S	14000 100% I
0%	100% 200%

20.2 Operating Area Set NPV

The operating area "Set NPV" is needed for synchronizing the axes and the workpiece.

Example:

The edge of the workpiece is scratched with a milling tool.

By pressing the softkey







the value for the current axis is colored.

Using the following softkeys, each axis can be "zeroed" ..



Also, using the machine keyboard, any value can be entered in the field that is currently selected, or with



the value of the axis can be set to zero.

20.3 Operating Area Zero Point Workpiece

The value is taken into account in the **active** zero point shift and entered in the zero point table

X 0.000
Y 150.000
Z 200.000

The screenshot shows the 'MANUELL' (Manual) mode of the ShopMill software. The 'Reset' button is active. The 'WKS' (Workpiece) table shows the following values:

WKS	Position	[mm]
X	0.000	
Y	150.000	
Z	200.000	

The 'T,F,S' (Tool, Feed, Spindle) table shows the following values:

T	F	S
Schaftfräuser_20 ø 20.000	0.000 0.000	100% mm/U
	0.000 0.000	0% 0

The 'G-Funktion' (G-Function) table shows the following values:

G-Funktion
Hilfs-Funktion
Alle G-Funk.
Laufzeiten

The bottom status bar shows various icons for 'T,S,M', 'NPV setzen', 'Nullp. Werkst.', 'Messen Werkz.', 'Schwenken', 'Position', and 'Planfräsen'.

In this operating mode, the value for the workpiece measurement can be written directly into the desired zero point shift.

ShopMill Version 6.4 offers many options for this.

Pressing the softkey

The screenshot shows the 'MANUELL' (Manual) mode of the ShopMill software. The 'Reset' button is active. The 'WKS' (Workpiece) table shows the following values:

WKS	Position	[mm]
X	0.000	
Y	150.000	
Z	200.000	

The 'T,F,S' (Tool, Feed, Spindle) table shows the following values:

T	F	S
Schaftfräuser_20 ø 20.000	0.000 0.000	100% mm/U
	0.000 0.000	0% 0

The 'G-Funktion' (G-Function) table shows the following values:


G-Funktion
Hilfs-Funktion
Alle G-Funk.
Laufzeiten

The bottom status bar shows various icons for 'T,S,M', 'NPV setzen', 'Nullp. Werkst.', 'Messen Werkz.', 'Schwenken', 'Position', and 'Planfräsen'. The 'Nullp. Werkst.' icon is highlighted.



offers five options for determining the zero point.

Edge




Corner



Drilling rectangular pocket



Spigot Rectangle




Aligning the plane




The described cycles can be utilized by using a manual touch probe or an automatic touch probe.


By pressing the softkey



the options for “Edge measurement” under ShopMill are displayed.




Pressing the softkey



opens the input screen form.
After selecting the zero point shift



and the axis





measurements can be made.

After the measurement is performed into <<?>> a non-active zero point, a query is displayed whether the zero point is to be activated.

By pressing the softkey



the input is accepted and the zero point is activated.




20.4 Measuring the Tool Length


By pressing the softky




in the operating area



and pressing the
softkey



the tool is measured by starting the workpiece in the length - Z – direction.




After selecting the tool

T Schaftfraeser_20 D1


selecting the reference point whether

Werkstück



or

Festpunkt



a tolerance can be entered after “scratching” the surface of the workpiece.

Z0 0.000 abs

By pressing the softkey


Länge setzen

the measured tool length is activated and accepted into the tool list.

20.5 Measuring the Tool Radius

Next, the tool's diameter is ascertained.

By pressing the
softkey




in the area “Measure tool”,

the corresponding
input screen form
opens.



After selecting the tool



a tolerance can be entered in reference to the tool edge in X and in Y.



After approaching the workpiece edge with the tool, the measured diameter is activated by pressing the softkey



and accepted into the tool list.

20.6 Swiveling

By pressing the softkey



in the operating area Manual

MANUELL			
Reset			
WKS	Position [mm]	T,F,S	
X	150.000	T Schaftfräser_20 Ø 20.000	D1 Werkzeuge
Y	150.000	F 0.000 100% 0.000 mm/U	Nullpunkt versch.
Z	0.000	S 0.000 0% 0.000	
		OK 100% 100%	
T,S,M...		Werkzeugname	
T D			
Spindel U/min			
Spindel M-Fkt.			
Sonst. M-Fkt.			
Nullpktv.			
Maßeinheit			
Werkzeugachse			
		Zurück	
<div> T,S,M NPV setzen Nullp. Werkst. Messen Werkz. Schwenken Position Planfräsen </div>			

the area for manual swiveling under ShopMill opens.

MANUELL			
Reset		Alternat.	
WKS	Position [mm]	T,F,S	
X	0.000	T	Werte Löschen
Y	0.000	F 0.000 115% 0.000 mm/U	
Z	100.000	S 0.000 100% 0.000 I	
A	0.000	OK 100% 200%	
C	0.000		
Schwenken		Schwenkdatensatz	
		TC KOPF_TISCH	
		Freifahren: Z	
		Schwenken neu	
		direkt	
		A 0.000 °	
		C 0.000 °	
		Zurück	
<div> T,S,M NPV setzen Nullp. Werkst. Messen Werkz. Schwenken Position Planfräsen </div>			

Manual swiveling under ShopMill is not part of the training document.

20.7 Manual Positioning

By pressing the softkey



in the operating area



MANUELL		Reset	
WKS	Position [mm]	T, F, S	
X	150.000	T	Schaftfräuser_20 D1
Y	150.000	F	20.000
Z	0.000	S	100% mm/U
			0.000 0.000 0%
T, S, M...		Werkzeugname	
T		D	
Spindel		U/min	
Spindel M-Fkt.			
Sonst. M-Fkt.			
Nullpktv.			
Maßeinheit			
Werkzeugachse			
		Zurück	

the target position is entered in the input fields.

X 230.000 abs
Y 230.000 abs
Z 120.000 abs

The travel motion can be entered in feed or

MANUELL		Reset	
WKS	Position [mm]	T, F, S	
X	150.000	T	Schaftfräuser_20 D1
Y	150.000	F	EILG. 100% mm/min
Z	0.000	S	0.000 0.000 0%
			0.000 0.000 0%
Positionieren		[mm/min]/[mm/U]	
X		230.000 abs	
Y		230.000 abs	
Z		120.000 abs	
F		* Eilgang * mm/min	
		Zurück	

F 0.200 mm/U

rapid feed

F * Eilgang * mm/min

.

There is no collision monitoring when the target position is approached.

20.8 Manual Face Milling

Pressing the softkey



in the operating area



opens the input field for the face milling cycle.

MANUELL		Reset	
WKS	Position [mm]	T, F, S	
X	150.000	T	Schaftfräser_20 D1
Y	150.000	F	Ø 20.000
Z	0.000	S	0.000 100% mm/U
			0.000 0%
T, S, M...		Werkzeugname	
T		D	
Spindel U/min			
Spindel M-Fkt.			
Sonst. M-Fkt.			
Nullpktv.			
Maßeinheit			
Werkzeugachse			
		Zurück	


This face milling cycle is described in greater detail in the chapter “Programming Example Standard Milling Cycle“.

MANUELL		Werkzeugname	
Planfräsen		D1	
T		D1	
F		0.000 mm/Zahn	
V		0 m/min	
Bearbeitung:			
Richtung:			
XB		0.000 abs	
YB		0.000 abs	
ZB		0.000 abs	
X1		1.000 ink	
Y1		1.000 ink	
Z1		1.000 ink	
DXY		0.100 mm	
DZ		0.100	
UZ		0.100	
		Abbruch	
Vorschub F zu klein		Plan-fräsen	

The face milling in the operating area Manual described above offers the only possibility to utilize a cycle under ShopMill 6.4 without having to create a program.

21 Measuring the Workpieces in the Setup Mode JOG - Milling

This module describes how to work in the setup mode with measuring cycles under ShopMill, using an example.



21.1 Measuring Manually – Measuring Automatically

Measuring Manually

When measuring the zero point manually, you have to move your tool manually to the workpiece. You can use edge probes, touch probes, or clock gauges whose radius and length is known. As an alternative, you can also use any tool with a known radius and a known length. However, the tools used for measuring must not be of the type 3DProbe.

Measuring Automatically

For automatic measuring, use exclusively electronic touch probes of the type 3D probes, or mono probes. The electronic touch probes have to be calibrated beforehand. For automatic measuring, preposition the probe first manually. After starting with the key "Cycle-Start", the probe is moved automatically with measuring feed to the workpiece and back again to the start position with rapid feed.

To be able to measure the workpiece zero point automatically, the machine manufacturer has to set up the measuring cycles beforehand.

Please take note of the machine manufacturer's data.

To obtain the desired measuring results, as a rule the sequence of the measuring points has to be noted that is shown in the help displays. Measuring points can be undone and then measured repeatedly. This is done by operating the softkey that is shown as being active (measuring value). For manual measuring, the reset can be made in any sequence; however, for automatic measuring only in the reverse measuring sequence.

Measuring Only

If you want to "only measure" the workpiece zero point, the measured values are displayed without the coordinate system being changed.

21.2 Measuring the Edge

When measuring an edge, you have the following options:

- Setting the edge

The workpiece is located on the work table parallel to the coordinate system. Measure one reference point in one of the axes (X, Y, Z).

- Setting up the edge

The workpiece is located randomly on the work table; that is, not parallel to the coordinate system. By measuring two points at the edge of the workpiece, you determine the angle to the coordinate system.

.

Distance 2 edges


The workpiece is located on the work table parallel to the coordinate system. Measure the distance L of two parallel workpiece edges in one of the axis (X, Y or Z) and determine its center.

Below, an example is used to describe how to measure the edge of a workpiece.

For “Measure Edge,”
press the softkey
below



and




and



or



or



With the





selection of

Nullpktv.

By pressing the
softkey



nur Messen



Pressing the arrow key



and



To change the axes,
press



or




For manual
measuring, approach
the workpiece with
the probe.

For automatic
measuring, approach
the workpiece closely
and press "CYCLE
START".



The position of the
workpiece edge is
calculated and
displayed.



21.3 Measuring the Corner

You have the option of measuring workpieces with an angle of 90° as well as with any angles.

- Measuring a right-angled corner

The workpiece has a 90° corner and is located randomly on the work table. By measuring 3 points, the corner point in the working plane (X/Y plane) is ascertained and the angle α between the reference edge at the workpiece (line through P1 and P2) and the reference axis (always the 1st axis of the work plane).

- Measuring any corner

The workpiece has any type of corner (not a rectangular one) and is located randomly on the work table. By measuring 4 points, we determine the following: the corner point in the work plane (X/Y plane), angle α between the reference edge at the workpiece (line through P1 and P2) and the reference axis (always the 1st axis of the work plane), and angle β of the corner.

Below, measuring a workpiece under one angle is described.

To measure the edge,
press



and



and



or



Press





and go to

Nullpktv.

Press



nur Messen



Measuring a Corner

To select “outside corner” “inside corner” press



Rechtwinklige Ecke	Außen- / Innen- Ecke
<p>Messwerte: α XB YB</p>	<p>nur Messen Ecke</p> <p>Außen- Ecke Lage 1</p>
<p>Messwerte: α XB YB</p>	<p>nur Messen Ecke</p> <p>Innen- Ecke Lage 1</p>

To select the corner, press



and



Rechtwinklige Ecke	Lage der Ecke
<p>Messwerte: α XB YB</p>	<p>nur Messen Ecke</p> <p>Innen- Ecke Lage 1</p>
<p>Messwerte: α XB YB</p>	<p>nur Messen Ecke</p> <p>Innen- Ecke Lage 2</p>
<p>Messwerte: α XB YB</p>	<p>nur Messen Ecke</p> <p>Innen- Ecke Lage 3</p>
<p>Messwerte: α XB YB</p>	<p>nur Messen Ecke</p> <p>Innen- Ecke Lage 4</p>

To measure “P1”
approach it and
press

P1 stored

**P1 ge-
speichert**

Repeat this for “P2”
and “P3”


**P2 ge-
speichert**

**P3 ge-
speichert**

For automatic
measurements, move
in front of the
measuring point and
press “CYCLE
START”



The corner point and
the angles α or β are
calculated and
displayed.



21.4 Measuring the Pocket and Hole

You have the option to measure rectangular pockets as well as several holes, and then align the workpiece.

- Measuring the rectangular pocket

The rectangular pocket has to be set up at a right angle to the coordinate system. By measuring 4 points within the pocket, the length, width and center of the pocket is ascertained.

- Measuring 1 hole

The workpiece is located randomly on the work table and has 1 hole. By means of 4 measuring points, we determine the diameter and the center of the hole.

- Measuring 2 holes

The workpiece is located randomly on the work table and has 2 holes. In both holes, 4 points respectively are measured automatically and from that the center of the holes is calculated. From the connection line between the two center points and the reference axis, angle α is calculated as well as the new zero point is determined that corresponds to the center of the 1st hole.

- Measuring 3 holes

The workpiece is located randomly on the work table and has 3 holes. In the 3 holes, 4 points respectively are measured automatically and from that, the center of the holes is calculated. A circle is placed through the three center points. From that, the center of the circle and the diameter of the circle are ascertained. When selecting a phase angle correction, the basic rotation α can be determined in addition.

- Measuring 4 holes

The workpiece is located randomly on the work table and has 4 holes. In the 4 holes, 4 points respectively are measured automatically and from that the center of the holes is calculated. Two centers respectively of a hole are connected diagonally. From that, the intersection of the two lines is determined. When selecting a phase angle correction, the basic rotation α can be determined in addition.


2, 3 and 4 holes can only be measured automatically.

Below, "Measuring a hole" is described.

To measure the diameter and the center point of a hole, press




and



and




or




or



or



or



Press





and select

Nullpktv.


Press




nur Messen



Go to “Hole diameter”



Select the “contact angle”.




Select the first point that is described in the menu as the first, and approach it.

For automatic measurement, move into the hole and press “CYCLE START”.



The diameter and the center point of the hole are calculated and displayed.



21.5 Measuring Spigots

You have the option to measure and align rectangular spigots, as well as one and several circular spigots:

- Measuring the rectangular spigot

The rectangular spigot is to be aligned right-angled to the coordinate system. By measuring 4 points at the spigot, we ascertain the length, width and the center point of the spigot.

- Measuring 1 circular spigot

The workpiece is located randomly on the work table and has 1 spigot. With 4 measuring points, we determine the diameter and the center point of the spigot.

- Measuring 2 circular spigots

The workpiece is located randomly on the work table and has 2 spigots. At the two spigots, 4 points respectively are measured automatically, and from that the center points of the spigots are calculated. From the connection line between the two center points and the reference axis, angle α is calculated and the new zero point is determined that corresponds to the center point of the first spigot.

- Measuring 3 circular spigots

The workpiece is located randomly on the work table and has 3 spigots. At the three spigots, 4 points respectively are measured automatically and from that, the center points of the spigots are calculated. A circle is placed through the three center points, and the center point of the circle and the diameter of the circle are ascertained. When selecting a phase angle correction, the basic rotation α can be determined in addition.

- Measuring 4 circular spigots

The workpiece is located randomly on the work table and has 4 spigots. At the four spigots, 4 points respectively are measured automatically and from that, the center points of the spigots are calculated. Two center points of the spigots respectively are connected diagonally, and then the intersection of both lines is determined. When selecting a phase angle correction, the basic rotation α can be determined in addition.


2, 3 and 4 circular spigots can only be measured automatically.

Below, measuring a spigot is described.


To measure the diameter or the center of a spigot, press




and




or




or




and



or



or



With the





go to the

Nullpktv.

and press



nur Messen



With the cursor, go to
Diameter Spigot
and press



Go to the value “DZ”
and press



Go the the contact
angle and press




Select the first point
that is described first in
the menu, and
approach it.

When measuring
automatically,
approach the
workpiece and press
“CYCLE START”.



The diameter and the center point of the spigot are calculated and displayed.



21.6 Aligning the Plane

You can measure a specially oblique plane of a workpiece, and ascertain the rotations α and β . With a subsequent coordinate rotation, the vertical alignment of the tool axis to the workpiece plane is possible. To determine the position of the plane in space, we measure in the tool axis at three different points. To align the tool axis vertically requires a tilting table or an inclinable head.

For the plane to be measured, the surface has to be even.


Below, measuring the oblique plane is described.

Aligning the Plane

To align and measure an oblique plane, press



and



. Press





. Go to

Nullpktv.

and press



nur Messen



Approach the first measuring point that is shown in the cycle, and save it.

**P1 ge-
speichert**

Then, approach the other points.


**P2 ge-
speichert**

**P3 ge-
speichert**

For automatic measuring, approach the tool and press



Angles α and β are calculated and displayed.




22 DIN/G-Code – Programming under ShopMill

In this module, programming in DIN under ShopMill is explained, using an example.

Under ShopMill, we can program in the so-called ISO G-code according to DIN 66025, and also with the cycles of the 840D.


When setting up a new program, the DIN editor under ShopMill is opened

by pressing the softkey



**G code
program**


The program example is generated by using the standard cycles.



G17– Machining plane XY plane
G41– Tool radius compensation (left)
G54– Active zero point shift
G90– Absolute measurement programming
G94– Feed in mm/min

The following G-functions are used for generating the program.

The workpiece below is to be programmed in G-code with cycle support.



In contrast to the standard cycles, the ShopMill cycles include the approach and retract strategy to the contour.




After entering the basic commands, calling the tool and after the approach position prior to processing, the corresponding cycle is opened by pressing the softkey



and




After entering the values and pressing the softkey



the cycle is closed and accepted.

Next, the contour is described.




22.1 Generating the Contour with the Contour Calculator

Pressing




opens the standard contour calculator.

After entering the values



Übernahme Element

the contour element is accepted as for ShopMill.




Element 1

**Gerade
vertikal**

To accept, press

**Übernahme
Element**




Element2

**Gerade
horizont.**

To accept, press

**Übernahme
Element**




Element 3

**Gerade
beliebig**

To accept, press

**Übernahme
Element**




Element 4

**Gerade
vertikal**

To accept, press

**Übernahme
Element**



Element 5

**Gerade
horizontal.**

To accept, press

**Übernahme
Element**

Element 6




**Gerade
vertikal**

To accept, press

**Übernahme
Element**

To accept the
contour, press

Übernahme



The contour is shown
as G-code.

```

PROGRAM
A231_DIN_D
G90 G90 G94 G40 G17
T="FRAESERG60"
M06
G94 S400 F270 M03 M08
G90 G54 G00 X-35.0 Y-35.0
CYCLE71(2,1,1,0,0,0,100,80,0,1,55,2,0.1,300,12,5)
G00 X-35.0 Y35.0
Z-10.0
G17 G90 DIAMOF ;*GP*
G1 X5 Y0 G41 ;*GP*
Y70 RND=10 ;*GP*
X72 ;*GP*
X92 Y58 ;*GP*
Y10 RND=15 ;*GP*
X5 ;*GP*
Y-25 G40 ;*GP*
==eof==
    
```

With the second tool,
the grooves are
made.

Go to the end of the
program

```
A231_DIN_D 37
M06[]
G94 S400 F270 M03 M08[]
G90 G54 G00 X-35.0 Y-35.0[]
[]
CYCLE71(2,1,1,0,0,0,100,80,0,1,55,2,0.1,300,12,5)[]
G00 X-35.0 Y35.0[]
Z-10.0[]
[]
G17 G90 DIAMOF ;*GP*[]
G1 X5 Y0 G41 ;*GP*[]
Y70 RND=10 ;*GP*[]
X72 ;*GP*[]
X92 Y58 ;*GP*[]
Y10 RND=15 ;*GP*[]
X5 ;*GP*[]
Y-25 G40 ;*GP*[]
[]
G00 Z2.0[]
Z100.0[]
[]
```

and set up a new tool
with the technology
data.

```
A231_DIN_D 41
G00 X-35.0 Y35.0[]
Z-10.0[]
[]
G17 G90 DIAMOF ;*GP*[]
G1 X5 Y0 G41 ;*GP*[]
Y70 RND=10 ;*GP*[]
X72 ;*GP*[]
X92 Y58 ;*GP*[]
Y10 RND=15 ;*GP*[]
X5 ;*GP*[]
Y-25 G40 ;*GP*[]
[]
G00 Z2.0[]
Z100.0[]
T="FRAESER6"[]
M06[]
G94 S4200 F150 M03 M08[]
G90 G54 G17 G00 X30.0 Y29.0[]
G00 Z2.0[]
==eof==
```

Then, the start
position is defined.


```
A231_DIN_D 50
X5 ;*GP*[]
Y-25 G40 ;*GP*[]
[]
G00 Z2.0[]
Z100.0[]
T="FRAESER6"[]
G94 S4200 F150 M03 M08[]
G90 G54 G17 G00 X30.0 Y29.0[]
G00 Z2.0[]
G01 Z-5.0[]
X70.0 F560[]
G00 Z2.0[]
X70.0 Y51.0[]
G01 Z-5.0 F150[]
X30.0 F560[]
G00 Z2.0[]
Z100.0 M05 M09[]
X-200.0 Y150.0[]
M30[]
==eof==
```

Pressing

Werkzeuge

opens the tool list of ShopMill.


After selecting the tool and pressing the softkey “into the program”, the tool is included in the program.




By pressing the softkey



the familiar simulation can also be started for a DIN program.



You have the option to change the view using different softkeys.



23 Multiple Clamping

The function "Multiple Clamping" optimizes the tool changes by means of several workpiece setups. This shortens the idle time since first, all machining of a tool is executed on all clampings prior to the next tool change being activated.

In addition to two-dimensional clamping, you can use the function "Multiple clamping" also for rotating clamping bridges. To this end, the machine has to have an additional rotary axis (for example, an A axis) or a dividing unit.

Please note the manufacturer's data regarding this.

Not only identical, but also differing workpieces can be processed with this function.

The function "*Multiple Clamping for Different Programs*" is a software option.

ShopMill generates automatically a single program from several programs.

The tool sequence within a program is retained.

Cycles and subprograms are not separated <<?>>

Position patterns are processed as a unit <<?>>.

The individual programs have to satisfy the following requirements:

- Only step sequence programs (no G-code programs)
- Programs have to be runnable
- Program of the 1st clamping has to be positioned
- No tags/repetitions; that is, no jumps in the program
- No inch/metric switching
- No zero point shifts
- No coordinate transformations (shifting, scaling, etc.)
- Contours have to have unique names; that means, the same contour name must not be called in several programs
- In the removal cycle (contour milling) the parameter "Starting point" must not be set to "manual".
- No modal settings; that means, settings that have an effect on all subsequent data blocks (only for multiple clamping for different programs)
- Max. 50 contours for each clamping
- Max. 99 clampings



Tags or repetitions that are not to be used in programs for multiple clamping can be circumvented by using subprograms.

Open the Program Manager.

Weiteres Mehrfachaufspg. <<additional, multiple clamping>>

-Press the softkey "Weiteres" and "Mehrfachaufspg.".

-Enter the number of clampings and the number of the first zero point shift that is to be used.

The clampings are processed in an ascending sequence starting with the **Start-Zero point shift**. The zero point shifts are defined in the menu "Werkzeuge/Nullpunktverschiebungen" <<tools/zero point shifts>> (refer to chapter "zero point shifts").

-Enter a **name for the new overall program** (XYZ.MPF).

-Press the softkey "OK".

A list is displayed in which the different programs have to be assigned to the zero point shifts. Programs don't have to be assigned to all zero point shifts -that is, clampings- but at least to two.

Press the softkey "**Program selection**".

The program overview is displayed.

-Place the cursor on the desired program.

-Press the softkey "OK".

The program is accepted into the assignment list.

-Repeat this process, until a program is assigned to each desired zero point shift.

-Press the softkey "**Auf alle Aufspg.**", if you want to process the same program on all clampings.

You also can assign different programs to individual zero point shifts first, and then assign the same program to the remaining zero point shifts by using the softkey

"Auf alle Aufspg." <<to all clampings>>

-Press the softkey "**Auswahl löschen**" <<clear selection>> or "**Alles löschen**",

if you want to remove individual or all programs from the assignment list.

-Press the softkey "**Programm berechnen**", <<calculate program>> when the assignment list is complete.

The tool changes are optimized.

Then, the overall program is renumbered consecutively, and when changing between different clampings, the number of the current clamping is specified.

In addition to the overall program (XYZ.MPF), the file XYZ_MCD.INI is set up where the assignment between zero point shifts and programs is stored. The two programs are stored in the directory that was previously selected in the program manager.

If you change from the assignment list (without "Cancel" or "Generate program") to another function and later you call the function "Multiple clamping" again, the same assignment list is displayed again.

24 CAD Reader

24.1 General Function

The CAD Reader is used for the following: to further edit drawings with the SINUMERIK controller that were constructed with a CAD system. As the format, a DXF file (**D**rawing **eX**change **F**ormat) is entered, and contours or drilling points are filtered out.

Parts that are not necessary for editing (such as dimensions, hatching, labeling, frames, etc.) can be removed. The generated contours or drilling patterns are implemented in a way that the geometry processor or cycle support understand them.

24.2 Opening the CAD READER


We are in the basic directory with the following softkeys:

- Machine
- Programs
- Program edit
- Alarm list
- Tool zero point

VERZEICHNIS					
Name	Typ	Geladen	Größe	Datum/Zeit	
BEISPIELPR	WPD	X	NCK-Dir.	19.03.2008	14:11
CAD_DXF	WPD	X	NCK-Dir.	15.02.2008	07:30
FORMPLATTE	WPD	X	NCK-Dir.	15.02.2008	07:28
SHOPM	WPD	X	NCK-Dir.	19.03.2008	14:12
TEMP	WPD	X	NCK-Dir.	28.03.2007	15:09

Freier Speicher Festplatte: 4.6 GBytes NC: 1336216

Ma- schine Pro- gramm Prog. edit NC Alarm- liste Werkz. Nullp.




With this arrow key toward the right, the softkey bar opens.



Press the softkey "CAD Reader"

24.3 Opening a DXF Drawing from a File.



24.4 Tool Bar



The tool bar can be selected by means of the global header with "View → Display Toolbar"


Operation in General

All functions of the CAD Reader can be operated with the keyboard as well as with the mouse. The right mouse key corresponds to the "ESCAPE" function that can be used for resetting activated menus or functions.

Operating sequence

Open DXFfiles


With **Open**, the selected CAD drawing is selected.



Saving the generated program


Generated contours can be saved as data type in the

- MPF format (□.mpf)
- SPF format (□.spf)
- ARC format (□.arc) (SINUMERIK archive)




Back

For contour tracking, the last action is reset corresponding to the selection element by element, or the last intersection is reset.



24.5 Specifying the Zero Point




To output the contour as NC program, it is necessary to specify a zero point of the drawing because in most cases, it will deviate from the zero point of the DXF file.

The following options are available to define the zero point:

Element Center	• Automatically to Element Center
Element Start	• Automatically to Element Start
Element End	• Automatically to Element End
Free Input	• Direct input of the coordinates; for example X100, Y100
Mouse Position	• Any position by selecting with the mouse

24.6 Contour Tracking

Setting the Contour Starting Point





Contour Tracking with starting point and end point

The starting and end point of the contour to be generated is selected in dependence of the initial position of the technology applied:

Element center	• Automatically to Element Center
Start/End point	• Automatically to Element Starting/Endpoint
Mouse position	• Directly with mouse selection


Example





Setting the contour end point

Element center
Element end point
Mouse position
Current position



1. Contour direction

Results from specifying the starting point • and additional contour selection. Regarding contour tracking the attempt is made to select the contour automatically to the greatest extent possible.

2. Selection if there is a conflict

If automatic contour tracking can no longer clearly determine a successor element, we switch to the interactive mode.

The user is prompted to specify the next element with which the contour continues.

3. Full circle as contour

With contour tracking, a full circle can be accepted in both directions.

4. Setting the end point

An end point can be set to any selected contour tracking element, and accepted.

Additional Notes

- Full circles can be accepted as contour or as drilling points.
- Contour tracking is canceled either with the keyboard with the "Esc" key, or with the right mouse key.

Setting the Contour Label

Prior to contour tracking, labels can be set by entering starting labels and end labels.


If a label is assigned twice, the CAD reader becomes interactive if the label was assigned once before.

- For contour tracking in contours already selected
- For appendixes to files if the label occurs already in the file.

Setting Drilling Points

1. Full circle as hole

A full circle can be selected with the function drilling points. The output of the generated G-code corresponds to the cycle format.




Any position
Row of holes
Hole circle
Grid of holes

Drilling Points Start

2. By selecting Drilling Pattern, drilling points can be parameterized as

- Any drilling position
- According to the cycle
- According to the cycle
- According to the cycle




Drilling Points End

3. Selected drilling points from the selection Drilling Pattern are accepted.

24.7 Influencing the Graphic Representation


Selecting the Processing Area:




If the file includes many additional drawings -such as profiles, measurements, hatching, labelings, detail displays, frames etc.- the selection of a processing area, the number of elements can be reduced with a "Lasso".

Deselecting the Processing Area:

The selections made in this processing area can be deselected.






Zoom/Keys “+” and “–”

You have the option to specify within a drawing a zoom area with the mouse key. By clicking on the symbol and using a "Lasso" or with the keys “+” and “–” the display area is enlarged or reduced step by step.

The display area can be moved using the cursor keys.

24.8 Editing Input Data



New Drawing/Spacer Bar

Reads out the current drawing anew and optimized corresponding to the layer selection.

Geometry


With a mouse click, the coordinates for the selected element are read out according to the current zero point. If the button Edit appears in the display screen form, this element can be edited by selecting this button.



Note

This function is suitable for minor changes in the geometry to remedy inadequacies (particularly missing intersections) in the CAD drawing.

For larger changes, the geometry processor is used. Once a change is made, it **can not** be reset.




Layer Selection

Initially, the selected DXF file is always shown with all its layers. If the file contains several layers, they are all shown in the basic view.


However, layers that don't contain data relevant to the contour can be hidden. Likewise, contours that are included in several layers can be selected by means of a selection screen form for contour tracking.

The layer selection can not be undone.




Rotating the Contour

By selecting this icon, the drawing is rotated by 90 degrees around the specified zero point, corresponding to the presets. Contour characteristics that have already been set are not rotated.



Displaying Hatching and Measurements

Hatching and measurements in the CAD drawings can be removed or displayed. Another click resets this function.




Deleting Contour Tracking

Defined contours can be selected and completely deleted. The function "Delete contour" is activated by selecting this icon and deactivated by selecting it again. Deleting finished contours:

Select icon: activate Delete contour

Select contour: contour is deleted




Deleting a Geometry Element

With this function, individual geometry elements can be deleted. The function "Delete geometry element" is activated by selecting this icon and deactivated by selecting it again. Deleting a geometry element:

Select: icon: activate Delete geometry element

Select elements: geometry elements are deleted



Deleting a Geometry Area


With a rectangle drawn with the mouse (corresponds to the area to be deleted) an entire area can be deleted from the geometry. This function is deactivated autonomously with each deletion, and has to be reactivated each time with this icon.

Select icon: Activate Delete geometry area

Select area: geometry area is deleted

24.9 Transferring Contour Elements to the Directory

- Save As
- SI_Train
- dh
- wks.dir
- Select directory where the contour is to be stored.




All contour elements are stored in the directory; for example, CAD_DXF.


VERZEICHNIS				
Name	Typ	Geladen	Größe	
BEISPIELPR	WPD	X	NCK-Dir.	
CAD_DXF	WPD	X	NCK-Dir.	
FORMPLATTE	WPD	X	NCK-Dir.	
SHOPM	WPD	X	NCK-Dir.	
TEMP	WPD	X	NCK-Dir.	

25 Sample Drawings - Milling


25.1 Mounting Plate




25.2 Hole Plate




25.3 Housing Lid




25.4 Longitudinal Guide



25.5 Example 1




25.6 Injection Mould




(Verwendungsbereich)				(Zul. Abw.)		(Oberfl.)		Maßstab 1:1		(Gewicht)	
								(Werkstoff, Halbzeug) (Rohteil-Nr) (Modell- oder Gesenk-Nr)			
					Datum	Name		SPRITZFORM			
				Bearb.	06.03.02	PURR					
				Gepr.							
				Norm							
				 Technologie Center <small>für CAD / Werkzeugmaschinenbau der Gesamthochschule</small>						Blatt	
										Blätter	
Zust.	Änderung	Datum	Name	Ursprung			Ersatz für:			Ersatz durch:	

25.7 Measuring Part




(Verwendungsbereich)				(Zul. Abw.)		(Oberfl.)		Maßstab 1:1		(Gewicht)	
								(Werkstoff, Halbzeug) (Rohteil-Nr) (Modell- oder Gesenk-Nr)			
					Datum	Name		<div style="text-align: center; font-size: 2em; font-weight: bold;">MESSE-TEIL</div>			
				Bearb.	21.02.02	KHE					
				Gepr.							
				Norm							
				 <div style="display: inline-block; vertical-align: middle;"> Technologie Center <small>Das Kfz-Zentrum für die Entwicklung der Zukunft</small> </div>						Blatt	
										Blätter	
Zust.	Änderung	Datum	Name	Ursprung		Ersatz für:			Ersatz durch:		


25.8 Pattern Plate



25.9 Exercise 11





26 Flange




(Verwendungsbereich)				(Zul. Abw.)		(Oberfl.)		Maßstab 1:1		(Gewicht)	
								(Werkstoff, Halbzeug) (Rohteil-Nr) (Modell- oder Gesenk-Nr)			
					Datum	Name		FLANSCH			
				Bearb.	06.03.02	PURR					
				Gepr.							
				Norm							
						Technologie Center		Blatt			
						Id. 001 - Weiterbildungsstelle des Siemens AG		Blätter			
Zust.	Änderung	Datum	Name	Ursprung	Ersatz für:				Ersatz durch:		

26.1 Clamping Plate




(Verwendungsbereich)				(Zul. Abw.)		(Oberfl.)		Maßstab 1:1		(Gewicht)	
								(Werkstoff, Halbzeug) (Rohteil-Nr) (Modell- oder Gesenk-Nr)			
					Datum	Name		<div style="text-align: center; font-size: 2em; font-weight: bold;">DRUCKPLATTE</div>			
				Bearb.	06.03.02	PURR					
				Gepr.							
				Norm							
				 <div style="display: inline-block; vertical-align: middle;"> Technologie Center <small>an der Fachhochschule für Technik</small> </div>						Blatt	
										Blätter	
Zust.	Änderung	Datum	Name	Ursprung			Ersatz für:			Ersatz durch:	


26.2 Prism




26.3 Kidney Plate




26.4 Connecting Rod



26.5 Wing



(Verwendungsbereich)				(Zul. Abw.)		(Oberfl.)		Maßstab 1:1		(Gewicht)		
								(Werkstoff, Halbzeug) (Rohteil-Nr) (Modell- oder Gesenk-Nr)				
					Datum	Name		FLUEGEL				
				Bearb.	06.03.02	PURR						
				Gepr.								
				Norm								
				 Technologie Center <small>(b. GbH, Verwaltungsgesellschaft der Studierenden)</small>				Blatt				
								Blätter				
Zust.	Änderung	Datum	Name	Ursprung	Ersatz für:				Ersatz durch:			