



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>CA/CSA/QAR16.0001/04</b>	Page 1 of 1
QAR Free Ref. No.:	<b>80047229 &amp; 80082126</b>	Status: <b>Issued</b>
Details of change:	Recertification Audit and Addition of Ex ec	Date of issue: <b>2021-08-02</b>
Site(s) audited:	<b>Siemens Canada Ltd.</b> 300 Applewood Crescent Concord Ontario L4K 5C7 <b>Canada</b>	Valid until: <b>2023-07-16</b>  Audit date: <b>2021-05-07</b>
Issuing ExCB:	<b>CSA - CSA Group</b>	
Manufacturer:	<b>Siemens Canada Ltd.</b> 300 Applewood Crescent Concord Ontario L4K 5C7	
Location of Manufacturer:	<b>Canada</b>	
Product information:	Communications equipment	
Protection concept:	<b>Ex ec nA &amp; nC</b>	
Related QARs:		
<a href="#">CA/CSA/QAR16.0001/00</a>	<a href="#">CA/CSA/QAR16.0001/01</a>	<a href="#">CA/CSA/QAR16.0001/02</a>
<a href="#">CA/CSA/QAR16.0001/03</a>		
Related Certificates (manual insertion)::		
<b>IECEX CSA 15.0029X</b>		
<b>IECEX CSA 16.0004X</b>		
<b>IECEX CSA 16.0005X</b>		
<b>IECEX CSA 16.0021X</b>		
<b>IECEX CSA 18.0007X</b>		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
<a href="#">IECEX CSA 15.0029X issue: 0</a>	<a href="#">IECEX CSA 15.0029X issue: 1</a>	<a href="#">IECEX CSA 16.0004X issue: 0</a>
<a href="#">IECEX CSA 16.0004X issue: 1</a>	<a href="#">IECEX CSA 16.0005X issue: 0</a>	<a href="#">IECEX CSA 16.0021X issue: 0</a>
<a href="#">IECEX CSA 18.0007X issue: 0</a>	<a href="#">IECEX CSA 21.0001X issue: 0</a>	
Comments:	Audit schedule has been aligned with Siemens Canada Limited (Peterborough) QAR number GB/SIR/QAR07.0039	