



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/SIR/QAR14.0015/04	Page 1 of 2
QAR Free Ref. No.:	80044292	Status: Issued
Details of change:	Recertification audit	Date of issue: 2020-09-28
Site(s) audited:	Siemens Aktiengesellschaft Oesterreich CEE RC-AT SIMEA IA-SC PLM2 SA Siemensstraße 90 1210 Wien Österreich Austria	Valid until: 2023-05-22
	Siemens SIMEA Sibui SRL 4 Florian Rieger Street 550052 Sibiu Romania	Audit date: 2020-06-30
Issuing ExCB:	SIR - SIRA Certification Service	
Manufacturer:	Siemens Aktiengesellschaft Oesterreich CEE RC-AT SIMEA IA-SC PLM2 SA Siemensstraße 90 1210 Wien Österreich	
Location of Manufacturer:	Austria	
Product information:	Power Supply	
Protection concept:	nA, nC, ec	
Related QARs:		
GB/SIR/QAR14.0015/00	GB/SIR/QAR14.0015/01	GB/SIR/QAR14.0015/02
GB/SIR/QAR14.0015/03		
Related Certificates (manual insertion):		
Related Certificates (automatic linking):		
Related Certificates for previous versions:		
IECEX EPS 14.0057X issue: 0	IECEX EPS 14.0057X issue: 1	IECEX EPS 14.0057X issue: 2
IECEX EPS 14.0057X issue: 3	IECEX EPS 14.0059X issue: 0	IECEX EPS 14.0059X issue: 1
IECEX EPS 14.0059X issue: 2	IECEX EPS 14.0059X issue: 3	IECEX EPS 14.0059X issue: 4
IECEX EPS 14.0062X issue: 0	IECEX EPS 14.0062X issue: 1	IECEX EPS 14.0063X issue: 0
IECEX EPS 14.0063X issue: 1	IECEX EPS 14.0065X issue: 0	IECEX EPS 14.0065X issue: 1
IECEX EPS 14.0066X issue: 0	IECEX EPS 14.0066X issue: 1	IECEX EPS 14.0066X issue: 2
IECEX EPS 14.0067X issue: 0	IECEX EPS 14.0067X issue: 1	IECEX EPS 14.0067X issue: 2
IECEX EPS 14.0067X issue: 3	IECEX EPS 14.0068X issue: 0	IECEX EPS 14.0069X issue: 0
IECEX EPS 14.0069X issue: 1	IECEX EPS 14.0069X issue: 2	IECEX EPS 14.0070X issue: 0
IECEX EPS 14.0070X issue: 1	IECEX EPS 14.0071X issue: 0	IECEX EPS 14.0071X issue: 1



IECEX Quality Assessment Report Summary

Related Certificates for
previous versions (continued):

IECEX EPS 14.0071X issue: 2
IECEX EPS 14.0077X issue: 0
IECEX EPS 15.0071X issue: 0
IECEX EPS 16.0047X issue: 1
IECEX EPS 16.0076X issue: 2
IECEX EPS 20.0011X issue: 1
IECEX PTZ 18.0001X issue: 0
IECEX QPS 16.0009X issue: 0

IECEX EPS 14.0072X issue: 0
IECEX EPS 14.0077X issue: 1
IECEX EPS 15.0071X issue: 1
IECEX EPS 16.0076X issue: 0
IECEX EPS 19.0083X issue: 0
IECEX EPS 20.0022X issue: 0
IECEX PTZ 19.0001X issue: 0
IECEX SIQ 20.0001X issue: 0

IECEX EPS 14.0072X issue: 1
IECEX EPS 14.0077X issue: 2
IECEX EPS 16.0047X issue: 0
IECEX EPS 16.0076X issue: 1
IECEX EPS 20.0011X issue: 0
IECEX PTZ 17.0004X issue: 0
IECEX QPS 16.0002X issue: 0

Comments: Initial QAR